## MARION COUNTY SURVEYOR'S OFFICE

SECTION CORNER RECORD

DEBRA S. JENKINS MARION COUNTY SURVEYOR

RR spike at surface

(fd 1999); previously a 1" iron pipe (7/8/1985)

SEC. 13 TWN.  $14_{\text{N}}$  RNG.  $2_{\text{E}}$ 

BRYAN F. CATLIN, PLS TECHNICAL SUPERVISOR

Date: 4-13-10 Party Chief: Wilcoxen Range Line 5300 W Crew: Finney Type of Marker: Survey mark nail Southport Rd 7500 Method of Establishment: County: 5-25-1999 IN S.P.C. E Zone, NAD 83 (1986) Name: 14021305 N: 489 423.727 0(m) E: 49 107.815 8(m) Crossfield Sub 3. F. Section 3  $\times - \times + \rightarrow \times$ Southport Road **Gravel Driveway** Detail 5.79 5/8' rebar down 2": previously a RR

THIS CORNER POSITION
REPRESENTS A "TITLE" CORNER
AND MAY NOT NECESSARILY
REPRESENT THE POSITION BASED
ON RECORD CORNERS.

Wilcoxen 10/28/1977 set PK nail per deed records. Wilcoxen 7/8/85 found PK nail. Kiste 9/19/94 found PK nail. Kiste 5/25/1999 set boat spike w/washer. Wilcoxen 8/28/2004 set survey mark nail. Wilcoxen 4/13/2010 called survey mark nail.

spike (10/28/1977)

REF	DISTANCE	DESCRIPTION
1.	28.49'	Mag nail SE side RR tie fence post
2.	31.25'	Mag nail w/brass washer NW PwP #16-744 48" up
3.	84.45'	Mag nail w/brass washer SW PwP #253-744B 24" up
4.	88.80'	Mag nail w/brass washer W PwP #1-744 B